

UNIT NUMBER SWMU 114

UNIT NAME Rubble pile 12

REGULATORY STATUS: AOC --

LOCATION: Culvert, Area 6 Boundary Road N-12200 W-3600

APPROXIMATE DIMENSIONS: 35 ft long, 20 ft wide, and 3 to 6 ft deep

FUNCTION: Stabilize roadway

OPERATIONAL STATUS: In place

DATES OPERATED: Unknown

SITE/PROCESS DESCRIPTION: Concrete slabs and bank gravel were used to construct road across 3-ft diameter pipe culvert and concrete rubble, and slabs were used above and below to control erosion.

WASTE DESCRIPTION: Concrete slabs and rubble - probably from PGDP road upgrading

WASTE QUANTITY: Approx. 40 cu yds of concrete

DESCRIPTION OF RELEASE: N/A

DOCUMENTATION OF NO RELEASE: Beta/Gamma scan found no detectable contamination on rubble. Gamma survey found no elevated soil readings.

RFI NECESSARY: YES



